

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

CHILD SEATS:

None during December 2013.

EQUIPMENT:

Extang Corporation (Extang) is recalling certain Encore Tonneau Covers sold as an aftermarket accessory for pick-up trucks. The Encore cover is a hard-panel, tri-fold cover whose front and rear panels open to allow access to the truck bed. The subject covers have a front panel that may become unsecured while driving, allowing wind to lift and separate the covers from the truck beds. If the cover separates from the truck bed, it may become a road hazard, increasing the risk of a crash. Extang will notify owners and arrange to install tether straps to secure the front panel cover to the truck bed, free of charge. The recall began on January 6, 2014. Customers may call 1-866-432-1329 or visit www.TruckbedCoverRecall.com for more information or to arrange for installation of the tether straps.

13E-066

Eaton Corporation (Eaton) is recalling certain Eaton and Fuller hybrid automated transmissions, part numbers EH-6E606B-CD; EH-6E606B-U; EH-6E606B-UP; EH-6E706B-UPG; EH-6E606B-T; EH-6E606B-CDG; EH-6E606B-P; EH-6E606B-CDR; EH-6E606B-PBD; EH-6E706B-PSB; EH-6E606B-PBD, that contain Eaton's hybrid control module software versions 5500682 or 5500683 and were manufactured August 30, 2010, through December 16, 2013 for use in medium-duty commercial vehicles. The software controlling the affected transmissions may improperly raise the vehicle's engine speed during downshifts without the driver's input. This can result in unintended acceleration during a downshift, increasing the risk of a crash. Eaton will notify their customers, who are medium-duty vehicle manufacturers and Eaton authorized service facilities will update the Hybrid Control Module Software version, free of charge. The recall is expected to begin by January 31, 2014. Customers may contact Eaton at 1-800-386-1911.

13E-068

Carflex Auto LTD in cooperation with Omix Ada, Inc. is recalling certain front and rear braided stainless steel replacement brake hoses sold as extended length replacement brake hoses for certain Jeep vehicles that have been modified for off road use. The brake hoses could leak fluid and possibly rupture. Failure of the brake hose would lengthen the distance required to stop the vehicle, increasing the risk of a crash. Omix Ada will notify wholesalers and owners, and will supply replacement brake hoses, free of charge. The recall is expected to begin by the end of January 2014. Owners may contact Omix Ada at 1-770-614-6101. Omix Ada's number for this recall is CBRK 1-13.

13E-069

Genera Corporation (Genera) is recalling certain aftermarket replacement tail lights, model 11-6468-00 (driver-side), and model 11-6467-00 (passenger-side), sold for use on 2012-2013 Toyota Prius V vehicles. The brake light and tail light circuits are switched causing the brake lights to be illuminated continuously until the brake pedal is pressed, when the brake lights will go out. The reversed tail lamp function reduces the ability to warn other motorists of the driver's intentions, increasing the risk of a crash. Genera will notify owners and provide replacement aftermarket tail lamps, free of charge. The recall is expected to begin in January 2014. Owners

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

may contact Genera at 1-888-963-9888. This recall is being conducted by Genera Corporation, not by Toyota Motor Corporation.

13E-070

Meritor, Inc. is recalling certain RMT14512ABS and RMT14612 trailer axles that were remanufactured for Trac Intermodal between June 1, 2013 and June 30, 2013. During remanufacturing, the axles may have been assembled with the lock washer and pin misaligned. The misalignment could prevent the pin from engaging. Additionally, the jam nut would not be torqued to specification, creating the potential for wheel separation, which could increase the risk of a crash. Meritor will notify Trac Intermodal, and Meritor service personnel will inspect and repair the axles, as necessary, free of charge. The recall is expected to begin on January 20, 2014. Owners may contact Meritor at 1-800-535-5560. Meritor's number for this recall is C14AB.

13E-071

Airstream, Inc. is recalling certain Fiamma-brand Flying Cloud and International model number 209397 accessory bicycle racks distributed January 2012 through December 2013 by Airstream. When the bike rack is installed as designed and loaded with bicycles, the secondary emergency exit in the rear of the trailer may be partially blocked. Partial blockage of the secondary emergency may hinder egress from the trailer in the event of an emergency, increasing the risk of injury to passengers. Airstream will notify owners, and will supply two new warning labels, one for the bike rack and one for inside the trailer by the rear secondary exit. This label will also come with installation instructions. The recall is expected to begin by early February 2014. Customers may contact Airstream at 1-937-538-1268.

13E-072

General Motors LLC (GM) is recalling certain software intended for 2015 vehicles that was installed by service centers into model year 2014 Chevrolet Silverados and GMC Sierras equipped with Allison A1000 transmissions. The incorrect software may cause the transmission indicator not to display that gear position "1" has been selected. As such, this vehicle does not conform to Federal Motor Vehicle Safety Standard (FMVSS) number 102, "Transmission Shift Lever Sequence, Starter Interlock, and Transmission Braking Effect." The transmission position indicator may not show that the transmission is in first gear (1) and not drive (D). If the drivers pulls into traffic, the vehicle's speed would be limited, resulting in an increased risk of a crash. GM will notify owners, and dealers will upload the correct transmission software, free of charge. The recall is expected to begin on January 17, 2014. Owners may contact Chevrolet at 1-800-222-1020 and GMC at 1-800-462-8782. General Motors' number for this recall is 13442.

13E-073

TIRES:

Michelin North America, Inc., (Michelin) is recalling certain Michelin LTX M/S tires, size LT225/75R16 115/112R LRE, manufactured from January 10, 2010, through June 23, 2012, and supplied for use as original equipment on certain Ford vehicles, and as replacement equipment on various brand commercial light trucks, full-sized heavy duty vans, small RVs and some large pickup trucks. These tires could experience tread separation. Tread separation can lead to rapid air loss, which may result in a loss of vehicle control, increasing the risk of a

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

crash. Michelin will notify owners and Michelin dealers will replace the tires free of charge. The recall began on January 6, 2014. Owners may call Michelin Consumer Care Monday-Friday from 8 a.m. to 8 p.m. EST, or Saturday and Sunday from 8:30am to 4:30pm EST at the following numbers: USA: 1-800-231-5893 (language options: English and Spanish)

13T-012

VEHICLES:

Spartan Motors, Inc. (Spartan) is recalling one model year 2006 Utilimaster vehicle manufactured on June 1, 2006 and equipped with a Fastec-brand door lock. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the cargo area at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Spartan will notify the owner, and Fastec will coordinate the inspection and replacement of the lock cylinder, as needed, free of charge. The recall began on January 8, 2014. Owners may contact Utilimaster at 1-800-582-3454 or Fastec at 1-800-837-2505.

13V-595

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2013-2014 Range Rover vehicles. In the affected vehicles, due to insufficient clearance, the Supplemental Restraint System (SRS) connector located in the driver and front passenger side seat of the vehicle may become disconnected. If the connector becomes disconnected, the driver and/or passenger seat side air bag may not function. In the event of a crash necessitating side air bag deployment, the seat occupant is at an increased risk of injury. Land Rover will notify owners, and dealers will modify the area around the connector to prevent it from becoming disconnected, free of charge. The recall is expected to begin on January 17, 2014. Customers may contact Land Rover at 1-800-637-6837, Option 9. Land Rover's number for this recall is P037.

13V-607

Triumph Motorcycles America Ltd (Triumph) is recalling certain model year 2013 Trophy SE motorcycles manufactured June 1, 2012, through February 28, 2013. In the affected motorcycles, the left hand center stand mount may fracture. If the center mount fractures, it will not provide adequate support for the center stand while the vehicle is parked and may cause the motorcycle to fall over, increasing the risk of injury to those nearby. Triumph will notify owners, and dealers will install a new center stand bracket to the left hand side of the motorcycle frame. The recall is expected to begin during January 2014. Customers may contact Triumph at 1-678-854-2010. Triumph's number for this recall is SB508RM2013/033.

13V-608

Starcraft RV, Inc. (Starcraft) is recalling certain model year 2014 16BH AR-ONE trailers manufactured between June 3, 2013, through September 30, 2013. The vehicles were built with tires of a lower load range than the Gross Vehicle Weight Rating requires. If the trailer is loaded to the gross vehicle weight rating that is listed on the label for the higher capacity tires, the tires may suddenly fail increasing the risk of a crash. Starcraft RV will notify owners and dealers will replace the tires and the spare tire with new ST175.80R13D tires and issue a correct tire label, free of charge. The recall began on January 8, 2014. Customers may contact Starcraft

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

at 1-800-945-4787.

13V-609

Chrysler Group LLC (Chrysler) is recalling certain model year 2013 Chrysler 300 AWD, Dodge Charger AWD, and Dodge Ram 1500 4x4 vehicles equipped with ZF all wheel drive ("AWD") 8HP45 transmissions. In the affected vehicles, the transmission output shaft may fracture. The transmission output shaft fracture could result in a loss of power, increasing the risk of a crash. Additionally, if the parking brake is not applied before exiting the vehicle, the vehicle may roll away despite the transmission being placed in 'Park'. Chrysler will notify owners, and dealers will inspect and replace the transmissions, as necessary, free of charge. The recall is to begin in January 2014. Customers may contact Chrysler at 1-800-853-1403. Chrysler's recall number is N65.

13V-610

Covered Wagon Trailers, LLC (Covered Wagon) is recalling certain model year 2006-2013 cargo trailers manufactured January 1, 2006, through April 25, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Covered Wagon will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin in January 2014. Owners may contact Covered Wagon at 1-229-423-4044 or Fastec at 1-800-837-2505.

13V-611

PACCAR Incorporated (Paccar) is recalling certain model year 2014 Kenworth T170, T270, T370, T440, T470, T660, T680, T700, T800, T880, C500 and W900 trucks manufactured July 1, 2013 through September 17, 2013. In the affected vehicles, the plastic housing of the Stop/Tail/Turn (STT) lamp can shrink and allow the light bulb to fall out of the mounted retention ring. As such, the Stop/Tail/Turn light would not be illuminated, and the vehicles do not conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 108 "Lamps, Reflective Devices, and Associated Equipment." If the stop/tail/turn light is not illuminated, the driver's intentions would not be communicated, which increases the risk of a crash. Kenworth will notify owners, and dealers will replace the defective STT lamps with new lamps. The recall is expected to begin in January 2014. Customers may contact Paccar at 1-425-468-7400. Kenworth's number for this recall is 13KWM.

13V-612

Spartan Motors Chassis, Inc. (Spartan Chassis) is recalling certain model year 2002 MetroStar, 2009 Gladiator, and 2013 Gladiator emergency response vehicles equipped with IMMI-brand L9 seat belt buckles. When the button is pressed to release the seat belt, the latch plate can become partially engaged with the buckle, making the seat belt difficult to unlatch. Thus, these vehicles fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 209, "Seat Belt Assemblies." If the latch plate remains partially engaged after the button is pressed, egress from the vehicle could be hindered, resulting in an increased risk of injury in the event of a crash or emergency. Spartan Chassis will notify owners, and dealers will inspect and replace the seat belt buckles, as necessary, free of charge. The recall is expected to begin in January 2014. Owners may contact Spartan at 1-517-543-6400. Spartan Chassis' number for this recall is 13026.

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

13V-613

Hino Motor Sales U.S.A. Inc. (Hino) is recalling certain model year 2011-2014 NE8J and NF8J trucks. In the affected vehicles, components of the parking brake handle assembly may wear resulting in either the parking brake unexpectedly releasing when engaged or preventing the parking brake from fully engaging. Either parking brake condition may result in the vehicle rolling unexpectedly, increasing the risk of a crash. Hino will notify owners, and when parts are available, dealers will install a newly designed parking brake lever assembly. Until parts are available, dealers will, as an interim measure, install a larger washer on the parking brake cable at the parking brake handle assembly. The interim repair notification is expected to begin in February 2014. A second notice will be mailed when the revised the parking brake assembly is available. Customers may contact Hino at 1-248-699-9330.

13V-614

General Motors LLC (GM) is recalling certain model year 2012-2013 Chevrolet Silverado HD and GMC Sierra HD vehicles, equipped with 6.6L diesel engines and dual fuel tanks. In the affected vehicles, the transfer pump which moves fuel from the rear tank to the front tank could malfunction and cause the fuel gauge to indicate an inaccurate reading. If the fuel gauge indicates an inaccurate reading it may result in the vehicle unexpectedly stalling, increasing the risk of a crash. General Motors will notify owners and dealers will inspect and replace the fuel transfer pump, as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet at 1-800-222-1020 and GMC at 1-800-462-8782. GM's number for this recall is 13420.

13V-615

Double R Trailer Mfg., Inc. (Double R) is recalling certain model year 2010-2014 utility trailers manufactured April 1, 2010, through December 6, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Double R will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin during January 2014. Owners may contact Double R at 1-208-461-7544 or Fastec at 1-800-837-2505.

13V-616

BMW of North America, LLC (BMW) is recalling certain model year 2005-2011 model year R-model motorcycles, model year 2005-2012 K-model motorcycles, model year 2010-2011 S 1000 model motorcycles, and model year 2006-2010 HP2 motorcycles. In the affected motorcycles, the fuel pump flange (and the auxiliary fuel pump flange if equipped) could develop cracks and leak fuel. A fuel leak in the presence of an ignition source may result in a fire. BMW will notify owners, and dealers will either reinforce the fuel pump flange or replace the pump, as necessary, free of charge. The recall is expected to begin in February 2014. Owners may contact BMW customer relations at 1-800-525-7417 or email BMW at CustomerRelations@bmwusa.com.

13V-617

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

American Honda Motor Company (Honda) is recalling certain model year 2014 Acura RLX vehicles manufactured August 7, 2012, through November 5, 2013. The bolts that attach the rear lower control arms to the sub-frame of the vehicle may have loosened during transport to dealerships. Loose rear lower control arm bolts may reduce steering ability, increasing the risk of a crash. Honda will notify owners, and dealers will replace the rear suspension lower control arm bolts, free of charge. The recall is expected to begin in early January 2014. Customers may contact Honda at 1-800-999-1009. Honda's number for this recall is JD0.

13V-622

Hino Motor Sales (Hino) is recalling certain model year 2013 NV8J vehicles manufactured November 13, 2012, through February 8, 2013. The affected vehicles were modified to have a lower Gross Vehicle Weight Rating (GVWR), however the vehicle documentation shows the full GVWR. As such, the information on the documents does not conform to Federal Motor Vehicle Safety Standards (FMVSS) Part 567 "Certification." An operator relying on the documents to determine the truck's GVWR may load the vehicle beyond the actual weight rating, possibly resulting in tire or suspension failure, increasing the risk of a crash. Hino will notify owners, and dealers will inspect and replace the documents, as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Customers may contact Hino at 1-248-699-9330. Hino's number for this recall is M0270.

13V-623

Hyundai is recalling certain model year 2014 Santa Fe vehicles manufactured November 5, 2013, through November 15, 2013, and equipped with P235/65R17 103T Continental Crosscontact LX tires. The tires may have a damaged sidewall. The damaged sidewall may result in a separation between the belt edges which could cause tread detachment or rapid air loss, increasing the risk of a crash. Hyundai notified dealers to suspend sales of affected Santa Fe Sport vehicles equipped with the P235/65R17 103T tires, and replace them with alternative tires. All affected vehicles were remedied prior to retail sale. Owners may contact Hyundai Customer Care Center at 1-800-633-5151.

13V-624

Monaco RV, LLC (Monaco) is recalling certain model year 2008-2013 recreational vehicles equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle without using the emergency exit, increasing the risk of injury. Monaco will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by mid-February 2014. Owners may contact Monaco at 1-877-466-6226 or Fastec at 1-800-837-2505.

13V-625

CJay Trailers Inc. (CJay) is recalling certain model year 2006-2013 CJ610, CJ612, CJ714, CJ716, CJ814, CJ816, CJ820, CJ823, and CJ824, model year 2007-2013 CJ510, model year 2008-2013 CJ813, model year 2010-2013 FX9-620 Combo and model year 2009-2013 CJ830 cargo trailers equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the trailer at the time will then

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

be locked in and be unable to exit the vehicle, increasing the risk of injury. CJay will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin in January 2014. Owners may contact CJay Trailers at 1-306-694-0445 or Fastec at 1-800-837-2505. CJay's number for this recall is R-12-2013.

13V-626

Daimler Trucks North America (DTNA) is recalling certain model year 2013-2014 Freightliner Cascadia trucks manufactured December 11, 2012, through November 27, 2013 and equipped with a Meritor Wabco electronically controlled air suspension (ECAS) system. In the affected vehicles, the wiring harnesses for the ECAS may have been reversed. If the wiring harnesses are connected in reverse, it may adjust the suspension axle height incorrectly, reducing driving traction and parking brake effectiveness. Either result increases the risk of a crash. DTNA will notify the owners, and dealers will inspect the ECAS wiring, correcting it as necessary, free of charge. The recall is expected to begin February 16, 2014. Owners may contact Daimler at 1-800-547-0712. DTNA's number for this recall is FL-656.

13V-627

Spartan Motors Chassis, Inc. (Spartan Chassis) is recalling certain model year 2006-2007 Diamond, model year 2006-2010 Gladiator, model year 2009-2010 Metrostar and one model year 2007 Advantage emergency response vehicles manufactured December 22, 2005, through October 13, 2010, and equipped with independent front suspensions (IFS) by Ridgewell Corporation. In the affected vehicles, welds on the IFS cradles may crack. Cracking of the welds could result in difficulty in steering the vehicle, increasing the risk of a crash. Spartan Chassis will notify owners, and dealers will repair any cracks and install reinforcement brackets, free of charge. An interim notification will be sent in January 2014. A second notification will be sent when the remedy parts are available. Owners may contact Spartan at 1-517-543-6400. Spartan's number for this recall is 13028.

13V-628

Contract Manufacturer, LLC (CM) is recalling certain model year 2006-2012 CM and S&H trailers equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. CM will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by mid-February 2014. Owners may contact CM Trailers at 1-888-268-7577 or Fastec at 1-800-837-2505.

13V-629

Navistar, Inc. is recalling certain model year 2014 IC Bus AE, BE and RE and model year 2014-2015 IC Bus CE school buses manufactured August 08, 2013, through November 14, 2013 and equipped with IMMI-brand L9 seat belt buckles. When the button is pressed to release the seat belt, the latch plate can become partially engaged with the buckle, making the seat belt difficult to unlatch. Thus, these vehicles fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 209, "Seat Belt Assemblies." If the latch plate remains partially engaged after the button is pressed, egress from the vehicle could be hindered, resulting in

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

an increased risk of injury in the event of a crash or emergency. Navistar will notify owners, and dealers will inspect and replace the seat belt buckles, as necessary, free of charge. The recall is expected to begin on February 18, 2014. Owners may contact Navistar at 1-800-448-7825. Navistar's numbers for this campaign are 13519 and 13520.

13V-630

Navistar Inc. is recalling certain model year 2014-2015 IC Bus CE and model year 2014 IC Bus RE transit buses manufactured August 12, 2013, through November 14, 2013 and equipped with IMMI-brand L9 seat belt buckles. When the button is pressed to release the seat belt, the latch plate can become partially engaged with the buckle, making the seat belt difficult to unlatch. Thus, these vehicles fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 209, "Seat Belt Assemblies." If the latch plate remains partially engaged after the button is pressed, egress from the vehicle could be hindered, resulting in an increased risk of injury in the event of a crash or emergency. Navistar will notify owners, and dealers will inspect and replace the seat belt buckles, as necessary, free of charge. The recall is expected to begin by February 18, 2014. Owners may contact Navistar at 1-800-448-7825. Navistar's number for this campaign is 13521.

13V-631

Airstream, Inc. (Airstream) is recalling 2013-2014 Airstream Interstate recreational vehicles manufactured August 2012 through October 2013. In the affected vehicles, the installation of the propane tank and the regulator may damage the regulator, allowing propane to escape out of the safety release vent if it experiences an over pressurized condition. If the vehicle is parked in an enclosed storage area, in the presence of an ignition source, the escaping propane can collect and potentially cause a fire and or explosion to occur. Airstream will notify owners, and dealers will replace the regulator on the propane tank, free of charge. The recall is expected to begin by early February 2014. Owners may contact the Airstream Warranty/Service Department by phone at 1-937-596-6111.

13V-632

Daimler Trucks North America (DTNA) is recalling certain model year 2011-2013 Thomas Built Saf-T-Liner C2 school buses manufactured December 3, 2009, through February 8, 2012, and equipped with Eaton hybrid automated transmissions. The software controlling the affected transmissions may improperly raise the vehicle's engine speed during downshifts without the driver's input. The increase in engine speed may result in unintended acceleration, increasing the risk of a crash. DTNA will notify owners and dealers will update the hybrid transmission software, free of charge. The recall is expected to begin by February 12, 2014. Owners may contact DTNA at 1-503-745-6910. DTNA's recall number is FL-657.

13V-633

Daimler Trucks North America (DTNA) is recalling certain model year 2009-2014 model year Freightliner Business Class M2 and Freightliner Custom Chassis MT45 and MT55 chassis manufactured August 27, 2008, through December 10, 2013 and equipped with Eaton hybrid automated transmissions. The software controlling the affected transmissions may improperly raise the vehicle's engine speed during downshifts without the driver's input. The increase in engine speed may result in unintended acceleration, increasing the risk of a crash. DTNA will notify owners and dealers will update the hybrid transmission software, free of charge. The recall is expected

SAFETY DEFECT/NONCOMPLIANCE NOTICES

RECEIVED DURING DECEMBER 2013

Published January 14, 2014

to begin by February 12, 2014. Owners may contact DTNA at 1-503-745-6910. DTNA's recall number is FL-657.

13V-634

Zero Motorcycles Inc. (Zero) is recalling certain model year 2012-2013 XU, S, DS, and model year 2013 FX motorcycles. The affected motorcycles have controller firmware that, as a result of certain system faults, may shut off power to the motor. A sudden loss of power to the motor may increase the risk of a crash. Zero will notify owners, and dealers will update the controller firmware, free of charge. The recall is expected to begin in mid-January 2014. Owners may contact Zero at 1-888-786-9376.

13V-635

Altec Industries Inc. (Altec) is recalling certain model year 2009-2013 DT80, and model year 2011-2013 D2, D3 and D4 digger derrick models manufactured June 2009 through November 2013. The fasteners that hold the bracket for the feeder tube (the telescopic hydraulic tube that supplies pump flow to the auger) may become loose allowing the feeder tube to fall. A falling feeder tube increases the risk of injury to people nearby. Altec will notify owners, and Altec service centers will install an upgraded feeder tube bracket and mounting hardware, free of charge. The recall is expected to begin in early February 2014. Owners may contact Altec at 1-877-462-5832. Altec's number for this recall is CSN 591.

13V-636

Marathon Homes Corporation (Marathon) is recalling certain model year 2006-2013 towable and fifth wheel travel trailers manufactured January 1, 2006, through April 25, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle without using the emergency exit, increasing the risk of injury. Marathon will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by early February 2014. Owners may contact Marathon Homes at 1-574-294-6441 or Fastec at 1-800-837-2505.

13V-637

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2013-2014 Allegro 33AA motorhomes equipped with an electric fireplace. In the affected vehicles, the fireplace may ignite a piece of exposed wood inside the electric fireplace. If the exposed piece of wood ignites, the rest of the motorhome could also catch fire. Tiffin will notify owners, and dealers will install a heat shield to keep heat from the exposed wood, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Tiffin at 1-256-356-8661.

13V-638

Daimler Trucks North America (DTNA) is recalling certain model year 2014-2015 Thomas Built Saf-T-Liner EFX school buses manufactured September 30, 2013, through November 15, 2013. In the affected vehicles, due to an incorrect calibration, the speedometer may display a speed lower than the vehicle is actually traveling. With the incorrect calibration, the driver may unknowingly exceed the posted speed limit, increasing the risk of a crash. DTNA will notify owners, and dealers will update the instrument cluster software to correct the

SAFETY DEFECT/NONCOMPLIANCE NOTICES

RECEIVED DURING DECEMBER 2013

Published January 14, 2014

calibration, free of charge. The recall is expected to begin on February 14, 2014. Owners may contact DTNA at 1-800-547-0712. DTNA's number for this recall is FL-658.

13V-639

Daimler Trucks North America (DTNA) is recalling certain model year 2014 Freightliner Custom Chassis MT45, MT55 and MBC Chassis manufactured September 24, 2013, through November 7, 2013. In the affected vehicles, due to an incorrect calibration, the speedometer may display a speed lower than the vehicle is actually traveling. With the incorrect calibration, the driver may unknowingly exceed the posted speed limit, increasing the risk of a crash. DTNA will notify owners, and dealers will update the instrument cluster software to the correct calibration, free of charge. The recall is expected to begin on February 14, 2014. Owners may contact DTNA at 1-800-547-0712. DTNA's number for this recall is FL-658.

13V-640

Mack Trucks, Inc. (Mack) is recalling certain model year 2014 CXU tractor trailers manufactured June 21, 2013, through October 4, 2013 and equipped with an automatic over-speed protection system. In the affected vehicles, the protection system, designed to monitor diesel engine speed and shutdown the engine should it rev excessively, may be wired incorrectly and may not operate as designed. Without a system to control the engine speed, if airborne hydrocarbons (combustible vapors) enter through the air intake, excessive engine speed may result in a catastrophic engine failure and/or engine fire. Mack will notify owners, and dealers will correct the system wiring, free of charge. The recall is expected to begin by mid-February 2014. Owners may contact Mack Trucks at 1-336-393-2000. Mack's number for this recall is SC0374.

13V-641

Nova Bus is recalling certain 2009-2012 model year LFS and LFS HEV transit buses equipped with Sure Power DC-DC converters containing a particular epoxy sealing, aka 'potting', compound. The specific potting compound used in the subject products for insulation was found to be capable of conducting electricity after being exposed to heat. Once electrically conductive, the material is capable of melting and burning, increasing the risk of a fire. Nova Bus will notify owners and dealers will inspect and replace the converters, as necessary, free of charge. The recall is expected to begin in January 2014. Owners may contact Nova Bus at 1-450-472-6410. Nova Bus's numbers for this recall are CR3030, CR3031, CR3032, CR3033 and CR3034 (depending on the converter's part number and location of in the vehicle).

13V-642

Blue Bird Corporation is recalling certain 2014-2015 model year All American and Vision school buses manufactured from September 24, 2013, through December 6, 2013. In the affected vehicles, a component within the hydraulic park brake pedal arm may not have been properly heat treated and may fracture causing the parking brake to release without warning. If the park brake pedal arm fractures, the bus may unexpectedly roll increasing the risk of personal injury or a vehicle crash. Blue Bird has notified owners and dealers will install a new parking brake assembly, free of charge. The recall began on December 31, 2013. Owners may contact Blue Bird at 1-478-822-2242. Blue Bird's number for this recall is R13WT.

13V-643

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

Cargo South, Inc. is recalling certain model year 2006-2013 enclosed utility trailers manufactured January 1, 2006, through April 25, 2013 and equipped with Fastec-brand door locks. In the affected trailers, it may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Cargo South will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by early February 2014. Owners may contact Cargo South at 1-229-468-5659 or Fastec at 1-800-837-2505.

13V-644

Nissan North America, Inc. (Nissan) is recalling certain 2014 model year Titan King Cab and Crew Cab pick-up trucks manufactured August 27, 2013, through November 13, 2013. In the affected vehicles, the Tire and Loading Information label overstates the maximum load and passenger carrying capacity of the vehicle. Thus, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims for Passenger Cars." If the vehicle is loaded to the capacity stated on the incorrect label, and the tire load capacity is exceeded, the vehicle may experience structural damage to the tire. If this occurs, this may lead to tire failure which could increase the risk of a crash. Nissan will notify owners and will provide owners with a correct label to install, free of charge. The recall is expected to begin on January 21, 2014. Owners may contact Nissan at 1-800-647-7261.

13V-645

Riverside Travel Trailer, Inc. (Riverside) is recalling certain model year 2006-2014 travel trailers manufactured January 1, 2010, through April 30, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle without using the emergency exit, increasing the risk of injury. Riverside will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin in January 2014. Owners may contact Riverside at 1-765-472-3920 or Fastec at 1-800-837-2505.

13V-646

Bay Bridge Manufacturing LLC (Bay Bridge) is recalling certain model year 2006-2013 cargo box vans and trailers manufactured January 1, 2006, through July 31, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Bay Bridge will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by early February 2014. Owners may contact Bay Bridge at 1-578-848-7477 or Fastec at 1-800-837-2505.

13V-647

Sharp Manufacturing is recalling certain model year 2006-2013 cargo trailers manufactured January 1, 2006, through April 30, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from

SAFETY DEFECT/NONCOMPLIANCE NOTICES
RECEIVED DURING DECEMBER 2013

Published January 14, 2014

the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the cargo trailer at the time will then be locked in and be unable to exit the vehicle, increasing the risk of injury. Sharp Manufacturing will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin on January 15, 2014. Owners may contact Sharp Manufacturing at 1-785-363-7336 or Fastec at 1-800-837-2505.

13V-648

Prevost Cars, Inc. (Prevost) is recalling certain model year 2012-2013 X3-45 VIP motorhomes, H3 VIP motorhomes and XLII-45 Entertainers and model year 2012-2014 model year X3-45, H3-41, H3-45 coaches manufactured June 6, 2011, through May 17, 2013, equipped with JAKO windshield wiper motors, model SWF403195. In the affected vehicles, the windshield wiper motor housing may crack resulting in a loss of windshield wiper function. Without functioning windshield wipers, the driver's visibility may be reduced, increasing the risk of a crash. Prevost will notify owners, and dealers will inspect the vehicles and any affected windshield wiper motor will be replaced, free of charge. The recall is expected to begin by the end of February 2014. Owners may contact Prevost at 1-418-883-2888. Prevost's number for this recall is SR14-02.

13V-650

Oshkosh Corporation is recalling certain model year 2013 S-Series ready mixed concrete trucks manufactured May 1, 2013, through November 27, 2013. In the affected vehicles, the brake pedal bracket may loosen due to missing lock washers. A loose brake pedal bracket may allow the brake pedal to contact the floor of the cab, which would reduce the vehicle's braking capability and increase the risk of a crash. Oshkosh will notify owners, and dealers will inspect and correct the brake pedal mounting assembly as necessary, free of charge. The recall is expected to begin in January 2014. Owners may contact Oshkosh at 1-888-686-7278.

13V-651

Skyline Corporation (Skyline) is recalling certain model year 2006-2013 recreational vehicle travel trailers and fifth-wheel trailers manufactured January 1, 2006, through May, 31, 2013 and equipped with Fastec-brand door locks. It may be possible to remove the key from the lock in a way that potentially jams the deadbolt. If the deadbolt jams, the interior side of the door lock may also jam. A person inside the travel trailer at the time will then be locked in and be unable to exit the vehicle without using the emergency exit, increasing the risk of injury. Skyline will notify owners, and Fastec will coordinate the inspection and replacement of the cylinders, as needed, free of charge. The recall is expected to begin by early February 2014. Owners may contact Skyline at 1-800-755-6521 or Fastec at 1-800-837-2505.

13V-652